


Engine 617.950



- Retighten nuts (arrows) on exhaust gas turbocharger.