

Engine 117 model year 1974, California Emission Control System

- Remove air filter.
- Soak a rag with cleaning fluid.
- Clean deposits on inside of throttle valve housing. Any sticking deposits should be removed with a nonmetallic scraper (for instance wood).
- Blow out vacuum connections on throttle valve housing with compressed air.

Make sure throttle valve moves freely.

